


Typical Perimeter Office Plan

Break Room
2 Conference Rooms
36 Offices
64 Work Stations



FROST TOWER
FORT WORTH

